

FIG. 1




FIG. 2




FIG. 3




FIG. 4

FIG. 5

FIG. 3

09254963.051401
T04T50" E9645260




FIG. 6

09549 0344
T04T50 E964560




FIG. 7

05493 054401
E9645850

92

THE CHANNELS OF
THE NEW USER
SERVICE ARE
ORDERED BY THEIR
DESIRED RECEPTION
QUALITY, SUCH AS
A SIR

FIG. 7A

94

DETERMINE
DOWNLINK
PHYSICAL
CHANNELS FOR A
REASSIGNMENT
USING A QUALITY
ESTIMATE

FIG. 7B

96

DETERMINE UPLINK
PHYSICAL
CHANNELS FOR
REASSIGNMENT
USING A
FRAGMENTATION
GAUGE

FIG. 7C

98

THE TIME SLOTS OF THE "BAD"
CCTVCH ARE ORDERED FROM
HIGH INTERFERENCE TO LOW
INTERFERENCE

100

IN THE TIME SLOT ORDER,
ATTEMPT TO REASSIGN PHYSICAL
CHANNELS IN DECREASING
ORDER OF REQUIRED SIR

FIG. 7D